

Quadratmaschengewebe

Mesh per inch (25,4 mm)	Maschen- weite w (mm)	Draht- stärke d (mm)	Offene Siebfläche $A_o = \left(\frac{w}{w+d}\right)^2 \times 100\%$	Maschen per cm	Maschen per cm ²	Gewicht (Stahl) kg/m ²
9	2,00	0,80	51%	4	13	2,90
9	2,00	0,90	48%	3	12	3,55
8	2,00	1,00	44%	3	11	4,23
8	2,00	1,20	39%	3	10	5,72
8	2,50	0,50	69%	3	11	1,06
8	2,50	0,71	61%	3	10	1,99
7	2,50	1,00	51%	3	8	3,63
7	3,15	0,56	72%	3	7	1,07
6	3,15	0,80	64%	3	6	2,06
6	3,15	1,20	52%	2	5	4,20
5	4,00	0,70	72%	2	5	1,32
5	4,00	1,00	64%	2	4	2,54
5	4,00	1,40	55%	2	3	4,61
5	4,00	1,60	51%	2	3	5,81
4	5,00	0,70	77%	2	3	1,09
4	5,00	0,90	72%	2	3	1,74
4	5,00	1,20	65%	2	3	2,95
4	5,00	1,60	57%	2	2	4,93
4	5,00	2,00	51%	1	2	7,26
3	6,30	1,00	74%	1	2	1,74
3	6,30	2,00	58%	1	1	6,12
3	7,00	2,00	60%	1	1	5,64
3	8,00	1,00	79%	1	1	1,41
3	8,00	1,20	76%	1	1	1,99
3	8,00	1,60	69%	1	1	3,39
3	8,00	2,00	64%	1	1	5,08
2	10,00	1,00	83%	1	1	1,15
2	10,00	1,40	77%	1	1	2,18
2	10,00	1,60	74%	1	1	2,80
2	10,00	1,80	72%	1	1	3,49
2	10,00	2,00	69%	1	1	4,23
2	10,00	2,50	64%	1	1	6,35
2	10,00	3,00	59%	1	1	8,79
2	12,50	2,00	74%	1	0	3,50
2	12,50	2,80	67%	1	0	6,51
1	15,00	2,00	78%	1	0	2,99
1	16,00	2,50	75%	1	0	4,29
1	20,00	2,00	83%	0	0	2,31
1	20,00	3,00	76%	0	0	4,97